WIRING DIAGRAMS

Fig. 2: Fuel Inj Ecu (LH 2.4), Ignition Coil (Grid 4-7)

1993 Volvo 940

For x

Copyright © 1998 Mitchell Repair Information Company, LLC

Friday, July 23, 2004 11:59PM